AGENDA

August 26-27, 2003 EPA/HSRC Meeting on Superfund Research

Hilton Cincinnati Netherland Plaza 35 West Fifth Street Cincinnati, OH 45202 513-421-9100

Purpose: Discuss current Hazardous Substance Research Center (HSRC) and U.S.

Environmental Protection Agency (EPA)/Office of Research and Development (ORD)

Superfund research, identify research needs, and foster collaborative efforts.

Tuesday, August 26, 2003

3, 0	•	
7:30 – 8:15 a.m.	Registration	
8:15 – 8:40 a.m.	Session 1: Welcome and Introduction Hugh McKinnon, Director, EPA/ORD/NRMRL Elaine Davies, Deputy Director, EPA/OSWER/OSRTI Steve Lingle, Director, EPA/NCER/EERD Charles Shackelford, Director, Rocky Mountain HSRC Mitch Lasat, EPA/ORD/NCER HSRC Project Officer	
8:40 – 8:50 a.m.	Break	
8:50 – 2:50 p.m.	Session 2: Ground Water Remediation and Monitoring Chairs: Lewis Semprini, Western Regional HSRC Bob Puls, EPA/ORD/NRMRL	
	8:50 – 9:10 a.m.	Benefits of DNAPL Source Reduction Lynn Wood, EPA/ORD/NRMRL
	9:10 – 9:30 a.m.	Thermal Remediation in Fractured Rock, Loring AFB Eva Davis, EPA/ORD/NRMRL
	9:30 – 9:50 a.m.	Monitored Natural Attenuation: Mechanisms for Chlorinated Solvents John Wilson, EPA/ORD/NRMRL
	9:50 – 10:10 a.m.	Developing a Framework for Monitored Natural Attenuation of Inorganic Contaminants in Ground Water Robert Ford, EPA/ORD/NRMRL
10:10 – 10:25 a.m.	Break	
	10:25 – 10:45 a.m.	Reactive Barrier Strategies for Metals in Ground Water

Rick Wilkin, EPA/ORD/NRMRL

	10:45 – 11:05 a.m.	Vapor Intrusion Dominic DiGiulio and Michelle Simon, EPA/ORD/NRMRL; Jim Weaver, EPA/ORD/NERL	
	11:05 – 11:25 a.m.	Biogeochemical Characterization of the Ground Water/Surface Water Interface: Potential Effects on the Fate of Arsenic Barth Smets and Allison McKay, Center for Hazardous Substances in Urban Environments	
	11:25 – 11:45 a.m.	Thermal Technique for Measuring Ground Water/Surface Water Interaction Bob Lien and Carl Enfield, EPA/ORD/NRMRL	
	11:45 – 12:05 p.m.	Cometabolic Biosparging of Solvents Lewis Semprini, Western Region HSRC	
12:05 – 1:10 p.m.	Lunch		
	1:10 – 1:30 p.m.	Anaerobic Degradation of Aromatic Hydrocarbons Martin Reinhard, Western Region HSRC	
	1:30 – 2:50 p.m.	Discussion: State of Science, Perspectives and Needs Facilitators: Ken Lovelace and Jim Cummings, EPA/OSWER/OSRTI; Dick Willey, EPA Region 1	
2:50 – 3:00 p.m.	Break		
3:00 – 5:00 p.m.	Session 3: Monitoring and Remediation of Contaminated Land Chairs: Fran Kremer, EPA/ORD/NRMRL, and Kathy Banks, Midwest HSRC		
	3:00 – 3:20 p.m.	State-of-the-Art in Containment Dave Carson, EPA/ORD/NRMRL	
	3:20 – 3:40 p.m.	Developing Options for Hydraulic Control and Source Treatment of Superfund Landfills Fran Kremer, John Wilson, EPA/ORD/NRMRL	
	3:40 – 4:00 p.m.	Methods for Monitoring Landfill Fugitive Air Emissions Susan Thorneloe and Bruce Harris, EPA/ORD/NRMRL	
	4:00 – 4:20 p.m.	Phytoremediation Research at the Midwest Hazardous Substance Research Center Katherine Banks, Midwest HSRC	
	4:20 – 4:40 p.m.	Managed Natural Attenuation; Monitoring and Modeling John Novak, Midwest HSRC	
	4:40 – 5:00 p.m.	Sorption and Mass Transfer Effects on Risk Assessment and Remediation Activities in Urban Settings William Ball, Isam Sabbah, and Edward Bouwer, Center for Hazardous Substances in Urban Environments	
5:00 p.m.	Adjourn		

Wednesday, August 27, 2003

8:20 – 11:10 a.m.	Section 2: Manifesting and Remodiction of Conteminated Land (Continue)		
8:20 – 11:10 a.m.	Session 3: Monitoring and Remediation of Contaminated Land (Continued)		
	8:20 – 8:40 a.m.	Soil Metal Bioavailability and Treatment Jim Ryan, Chris Impellitteri, and Kirk Scheckel, EPA/ORD/NRMRL	
	8:40 – 9:00 a.m.	Soil Characterization and Sampling Jeff VanEe, EPA/ORD/NERL	
	9:00 – 9:20 a.m.	Overview of EPA's Mining Waste Technology Program Roger Wilmoth, EPA/ORD/NRMRL	
	9:20 – 9:40 a.m.	Evaluation of Hydrologic Models for Alternative Covers at Mine Waste Sites Chuck Shackelford, Rocky Mountain Regional HSRC	
9:40 – 9:50 a.m.	Break		
	9:50 – 11:10 a.m.	Discussion: State of Science, Perspectives and Needs Facilitators: Ken Skahn and Deana Crumbling, EPA/OSWER/OSRTI	
11:10 – 11:20 a.m.	Break		
11:20 – 4:00 p.m.	Session 4: Contaminated Sediments Chairs: Danny Reible, S&SW HSRC, and Dennis Timberlake, EPA/ORD/NRMRL		
	11:20 – 11:40 a.m.	A Contaminated Sediment Cap: Wizzard or Dunce? Danny Reible, S&SW HSRC	
	11:40 – 12:00 noon	Metals and Organics Release from Resuspended Sediments Louis Thibodeaux and Mason Tomson, S&SW HSRC	
12:00 – 1:00 p.m.	Lunch		
	1:00 – 1:20 p.m.	Evaluating the effectiveness of Monitored Natural Attenuation Dick Brenner, EPA/ORD/NRMRL; Jim Lazorchak, EPA/ORD/NERL; Joe Schubauer-Berrigan, EPA/ORD/NRMRL	
	1:20 – 1:40 p.m.	Fate and Transport of Metals and Sediment in Surface Water Pierre Julien, Rocky Mountain Regional HSRC	
	1:40 – 2:00 p.m.	Fate and Transport Modeling Earl Hayter, EPA/ORD/NERL, and Dave Mount, EPA/ORD/NHEERL	
	2:00 – 2:20 p.m.	Tiered Risk Assessment Dave Mount and Larry Burkhard, EPA/ORD/NHEERL	

2:20 - 2:40 p.m. **Characterizing the Ecological Risks of Dredging**

Contaminated Sediments

Mike Kravitz, EPA/ORD/NCEA, and Dennis Timberlake,

EPA/ORD/NRMRL

Discussion: State of Science, Perspectives and Needs Facilitators: TBD 2:40 - 4:00 p.m.

General Discussion: Overview and Action Items 4:00 - 4:20 p.m.

4:20 Adjourn